Core Return Policy



The TRC Core Return Policy includes:

- Prepaid Freight on all qualifying core returns
- All necessary paperwork included with every unit
- Pre-filled out Bill of Lading to streamline returns

Core Return Policy

- Cores must be returned within **6 months** of the original invoice date to be eligible for credit.
- Cores must be the same model as the unit purchased; "Like for Like".
- Cores must be completely drained of all oil.
- Cores must be **fully assembled** and have **no missing parts.**
- Cores must have a core return tag attached to the core to receive full credit (figure 1a & 1b).
- Must have a **minimum of 2 cores per pallet** to be eligible for prepaid core return (figure 1a).
 - A \$75 charge will be issued on single core pallets returned.
- If multiple pallets returned under one BOL include copy of BOL with **each** pallet in a document bag (figure 1a).
- **Contact the Designated Carrier** provided on the Bill of Lading (figure 2) to **schedule a pick up.** Failure to use the designated carrier will result in a charge back for the difference in freight cost.

Adhering to this procedure will ensure your core returns and credits are processed within 72 hours of core receipt. Failure to abide by this procedure will result in credit ineligibility or delays.

	Manual		Automatic Manual		Allison Legacy Transmission		Allison World Transmission (1000, 2000, 3000		Light Duty Automatic					
Core Return Description	Transmission		Transmission		(AT, MT, HT)		4000 Series)		Transmission		Differential		Steering	
Unit does not rotate Freely	\$	750	\$	750		N/A		N/A		N/A	\$	250	\$	150
Cracked Case or Excessive Rust	\$	750	\$	750	\$	400	\$	750	\$	400	\$	250	\$	150
Missing Parts	\$	175	\$	175	\$	175	\$	175	\$	175	\$	175	\$	175
Disassembled Core	\$	125	\$	125	\$	125	\$	125	\$	125	\$	125	\$	125
Failure to Drain Oil	\$	100	\$	100	\$	100	\$	100	\$	100	\$	100	\$	100
Less than 2 cores on a pallet	\$	75	\$	75	\$	75	\$	75	\$	75	\$	75	\$	75

Core Credit Reduction Table

Disclaimer

Any Transmission, Differential or Steering gear that is burnt up, has bulging cases, units that have been exposed to fire or units that have severe rust as a result of prolonged weather exposure will not be acceptable for any core credit.









Note: If you are missing a Core Return Tag, contact the Call Center or download a replacement Core Return Tag at <u>www.trcreman.com/promotionsandliterature.php</u>. Required info to be filled in by the customer.





Note: If you are missing the Bill of Lading, contact the Call Center.